


Problems Previously Identified in the IH 35 PEL Study Area (Exhibit 1)



Please place a green dot next to the items that you believe are problems, and a red dot next to those that you do not believe are problems.

Conflicts between local and through traffic on I-410 and IH 35	
Left side freeway exit ramps	
Traffic demand exceeds capacity on IH 35 and adjacent local street system	
Congestion increases the potential for accidents	
Poor pavement conditions on some sections on IH 35	
Poor traffic flows at both interchanges between IH 35 and I-410	
High number of trucks use the corridor	
Limited bicycle and pedestrian facilities within the corridor	

Less **time** in traffic

More **time** for you

It's **time** to take action



www.TimeFor35.com

