


Problems Previously Identified in the IH 35 PEL Study Area (Exhibit 2)



Please place a green dot next to the items that you believe are problems, and a red dot next to those that you do not believe are problems.

Cars and trucks inhibit each other's movements	
No alternate routes for truck through-traffic	
Limited transportation choices within the corridor	
Existing Randolph "park and ride" lot not easily accessible	
Single-lane exit ramps are not adequate for today's traffic volumes	
Lack of bicycle and pedestrian facilities to connect employment centers and shopping to residential areas	
Rail lines inhibit traffic at crossings on adjacent arterial streets	
Increasing rail traffic in the corridor	

Less **time** in traffic

More **time** for you

It's **time** to take action



www.TimeFor35.com

